



LLP-LXH2015150









- 1. SSH-LLP2015150, LIGHT PIPE HOLDER.
- 2. LLP-LXV2D15150, LIGHT PIPE.
- 3. PARTS ARE SUPPLIED SEPARATELY.

UNCONTROLLED DOCUMENT

*TOLERANCES PER DECINAL PRECISION ARE: X=±1 (±0,039), X.X=±0.5 (±0,020), X.XX=±0.25 (±0.010),

REV. PART NUMBER LLP-LXH2015150

LIGHT PIPE HOLDER ASSEMBLY.

Confidential information

The information contained in this document is the property of Lumex No. Except as specifically authorized in writing by Lumex Inc., the holder of this document shall keep all information contained herein confidential and shall protect same in whole or IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

 $\begin{array}{c} \underline{\text{Reliablity Note}} \\ \text{Our nany years of experience data accumulation indicate that} \end{array}$ SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



290 E. HELLEN ROAD PALATINE, ILLINOIS 60067 PHONE: (847) 359-2790 WEB: http://www.lumex.com

CHECKED BY: APPROVED BY: DATE: 3-1-00

> PAGE: 1 OF 1 SCALE: N/A

SS/BC