

UNCONTROLLED DOCUMENT


PART NUMBER

LXP-CARRIER24-56





9.35 [0.368] -



*TOLERANCES PER DECIMAL PRECISON ARE: X=±1 (±0.039), X.X=±0.5 (±0.020), X.XX=±0.25 (±0.010).

REV.

4.90 [0.193]

PART NUMBER LXP-CARRIER24-56

CARRIER TAPE FOR 305 AND 306 ASSEMBLIES.

CONFIDENTIAL INFORMATION
THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC.. THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

⊢ 2.66 [0.105]

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



290 E. HELLEN ROAD PALATINE, ILLINOIS 60067 PHONE: (847) 359-2790 WEB: http://www.lumex.com

DRAWN BY:

CHECKED BY: APPROVED BY: DATE: 1-24-00 PAGE: 1 OF 1

> SCALE: N/A

REV.

CK/DU