1.70 [0.067] [

 $3.30^{+0.10}_{0.00}$ $\left[0.130^{+0.004}_{0.000} \right]$

6.60 [0.260]

 $1.70^{+0.10}_{0.00} \ [\ 0.067^{+0.004}_{0.000}]$

Ø2.90 [Ø0.114]

C.XAM)

DETAIL A

0.60 [0.024]

- 3.90 [0.154]

1.60 [0.063]

1.10 [0.043]

C.XAM)

SC:0.50


PART NUMBER


LXP-LNR2124

REV.


PRELIMINARY IN P/N DIR PATENT PENDING

DETAIL VIEW A





DETAIL VIEW B



UNCONTROLLED DOC

LEAD LENGTH=±0.75 (±0,030). MIN= +DECINAL PRECISION *UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECINAL PRECISION ARE: X=±1 (±0.039), XX=±0.5 (±0.020), XXX=±0.25 (±0.010), XXXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002),

REV.

LXP-LNR2124

LENS FOR TWO HIGH SMT FAULT INDICATOR, SMF-R2124.

CONFIDENTIAL INFORMATION
THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROFERTY OF
LUMEX NO. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX
INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION
CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THRO PARTIES.

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.




GB/CK

290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com TW WEB: www.lumex.com.tw

DRAWN BY: CHECKED BY:

APPROVED BY:

DATE: 11.12.03 PAGE: 1 OF 1 SCALE: N/A





PART NUMBER

RELIABILITY NOTE PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.