UNCONTROLLED DOCUMENT SC:1.5 PART NUMBER REV. LCM-960234-56 – 151.00 [5.945] *–* PRELIMINARY IN P/N DIR - 135.10 [5.319] -2.00 [0.079] 7.50 [0.295] [0.918] [0.807] - 114.88 [4.523] -23.31 20.50 0 [3,740] [3,398] 80,00 [3,150] 110.00 [4.331] 95,00 31 [0,640] 86. 16,26 0 ø3.20 [ø0.126] UNCONTROLLED DOCUMENT *UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECINAL PRECISION ARE: X=±1 (±0.039), XXX=±0.5 (±0.020), XXX=±0.25 (±0.010), XXXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). NN=+0.000 (±0.030), NN=+0.000 CONFIDENTIAL INFORMATION
THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF 290 E. HELEN ROAD PALATINE, IL 60067–6976 PHONE: +1.847.359.2790 REV. PART NUMBER LIMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WIRTING BY LUMEX INC, THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR LCM-960234-56 US WEB: www.lumex.com IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES. TW WEB: www.lumex.com.tw $\begin{array}{c} \underline{\text{Reliablity Note}} \\ \text{Our nany years of experience data accumulation indicate that} \end{array}$ DRAWN BY: CHECKED BY: APPROVED BY: DATE: 01.21.08 PAGE: 1 OF 1 SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS. SCALE: N/A