UNCONTROLLED DOCUMENT SC:0.50 PART NUMBER REV. LLP-C102625S PRELIMINARY IN P/N DIR 44.33 [1.745] 0.40 [0.016] NOTES: 1.10 [0.043] 1. MATERIAL: CLEAR PC 2. TOP SURFACE DIFFUSED. R3.13 [R0.123] 3. BOTTOM SURFACE IS SMOOTH FINISH. R3.53 [R0.139] 1.20 [0.047] UNCONTROLLED DOCUMENT *UNILESS OTHERWISE SPECIFIED TOLERANCES PER DECINAL PRECISION ARE: X=±1 (±0.039), XXX=±0.5 (±0.020), XXX=±0.25 (±0.010), XXXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). MIN= +DECINAL PRECISION MAX.= +0.00 (±0.000), XXX=±0.127 (±0.000), XXXX=±0.127 (±0.000), XXXX=±0.000, XXX=±0.000, XXX=±0.00 CONFIDENTIAL INFORMATION

THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX NO. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR 290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 REV. PART NUMBER LLP-C102625S US WEB: www.lumex.com IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES. TW WEB: www.lumex.com.tw $\begin{array}{c} \underline{\text{Reliablity Note}} \\ \text{Our nany years of experience data accumulation indicate that} \end{array}$ DRAWN BY: CHECKED BY: APPROVED BY: DATE: 11.04.04 LIGHT PIPE. PAGE: 1 OF 1 SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.

PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

SCALE:

N/A