

UNCONTROLLED DOCUMENT


SC:1

PART NUMBER

LPA - C0822130S - NM

REV.

PRELIMINARY IN P/N DIR



UNCONTROLLED DOCUMENT

*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X= .1 (.039), X.X= .05 (.020), X.XX= .025 (.010), X.XXX= .0127 (.005). LEAD SIZE= .05 (.002), LEAD LENGTH= .75 (.030), MIN= .00, MAX= .00.

REV.	PART NUMBER LPA - C0822130S - NM	CONFIDENTIAL INFORMATION THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.	 290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com TW WEB: www.lumex.com.tw
8 COLUMN BY 2 ROW CUSTOM LIGHTPIPE		RELIABILITY NOTE OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.	
		DRAWN BY: Jakabn	CHECKED BY: APPROVED BY: DATE: 7/21/2009 PAGE: OF SCALE: N/A