

UNCONTROLLED DOCUMENT COMPANY CONFIDENTIAL



SC:1

PART NUMBER

LPA - LXC71178

REV.

PRELIMINARY IN P/N DIR



C M C3 C3 UNCONTROLLED DOCUMENT

*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X= .1 (.039), X.X= .05 (.020), X.XX= .025 (.010), X.XXX= .0127 (.005). LEAD SIZE= .05 (.002), LEAD LENGTH= .75 (.030). MIN= +DECIMAL PRECISION -0.00 MAX. = +0.00 -DECIMAL PRECISION

REV.	PART NUMBER LPA - LXC71178	CONFIDENTIAL INFORMATION THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES. RELIABILITY NOTE OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.		LUMEX An ITW Company OPTO 290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com TW WEB: www.lumex.com.tw	
CUSTOM EYEBROW LIGHTPIPE		DRAWN BY: JN	CHECKED BY:	APPROVED BY:	DATE: 11/7/2008 PAGE: 1 OF 1 SCALE: N/A

UNCONTROLLED DOCUMENT COMPANY CONFIDENTIAL





SC:1

PART NUMBER

LPA - LXC71178

REV.

PRELIMINARY IN P/N DIR



CM C3 C3 UNCONTROLLED DOCUMENT

*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X= .1 (.039), X.X= .5 (.020), X.XX= .25 (.010), X.XXX= .127 (.005). LEAD SIZE= .05 (.002), LEAD LENGTH= .75 (.030). MIN= +DECIMAL PRECISION -0.00 MAX. = +0.00 -DECIMAL PRECISION

REV.

PART NUMBER
LPA - LXC71178

CUSTOM EYEBROW LIGHTPIPE

CONFIDENTIAL INFORMATION

THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



290 E. HELEN ROAD
PALATINE, IL 60067-6976
PHONE: +1.847.359.2790
US WEB: www.lumex.com
TW WEB: www.lumex.com.tw

DRAWN BY:

JN

CHECKED BY:

APPROVED BY:

DATE: 11/7/2008

PAGE: 1 OF 1

SCALE: N/A