UNCONTROLLED DOCUMENT SC:0.50 PART NUMBER LPF-C014303S PRELIMINARY IN P/N DIR. 4.00 [0.157] -Ø3.00 [Ø0.118] (4 PLS.) 5.08 [0.200] (3 PLS.) 21.82 [0.859] 5.08 [0.200] 3.40 [0.134] 25.00 [0.984] -**→** 3.60 [0.142] Ø1.10 [Ø0.043] (2 PLS.) 26.80 [1.055] CONFIDENTIAL INFORMATION 290 E. HELEN ROAD REV. PART NUMBER THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX PALATINE, IL 60067-6976 LPF-C014303S PHONE: +1.847.359.2790 INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION US WEB: www.lumex.com CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR TW WEB: www.lumex.com.tw IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES. RELIABILITY NOTE CHECKED BY: APPROVED BY: DATE: DRAWN BY: 3.5.04 OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT 4 HIGH, RIGHT ANGLE LIGHT PIPE, 3mm ROUND LENS. PAGE: 1 OF 1 SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS. SCALE: N/A