




- NOTES:
- 1. PAGE 1: Lumex Inc. We tame photons to work for you.
 - 2. PAGE 2: Please contact our local sales rep or distributor for details.
 - 3. THE MESSAGES SHOULD GO BACK AND FORTH BETWEEN PAGES.
 - 4. THE DISPLAY SHOULD HAVE A MALE PIN HEADER IN CONJUNCTION WITH FEMALE CONNECTOR FOR EASY INSTALLATION AND REPLACEMENT.
 - 5. THE BOX MATERIAL WILL BE THE SAME THAT TERKI SENT TO LUMEX. (ELECTRICITY WOOD)
 - 6. BOTH OPTIONS ON THE DISPLAY CASE, WITH BATTERY AND WITH REGULAR 110V POWER.

*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X=±1 (±0.039), XX=±0.5 (±0.020), XXX=±0.25 (±0.010), XXXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). MIN= +DECIMAL PRECISION -0.00 MAX.= +0.00 -DECIMAL PRECISION

REV.	PART NUMBER LXP-DISPLAYBOX3	CONFIDENTIAL INFORMATION THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.	 290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com TW WEB: www.lumex.com.tw	
CHARACTER MODULE BOX.		RELIABILITY NOTE OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.	DRAWN BY: CT	CHECKED BY: APPROVED BY: DATE: 7.30.01 PAGE: 3 OF 4 SCALE: N/A