



UNCONTROLLED DOCUMENT


(X) PART NUMBER		REV.
LXP-TUBE-05		A
REV.	E.C.N. NUMBER AND REVISION COMMENTS	DATE
A	E.C.N. #10BRDR. & ADDED 'LXHM140'	7-13-99



NOTES:

1. TUBES: CLEAR RIGID ANTISTATIC PVC.
2. RUBBER PLUG (2PCS).
3. SFX-LXH307M (87 PCS/TUBE).
4. SSF-LXHM140-39922 (15 PCS/TUBE).
5. PARTS ON HIDDEN LAYERS PER PART NAME.

DETAIL A



UNCONTROLLED DOCUMENT

*UNLESS OTHERWISE SPECIFIED TOLERANCE IS ±0.25mm (±0.010")

REV.	PART NUMBER
A	LXP-TUBE-05
TUBE PACK FOR SFX-LXH307M AND SSF-LXHM140-39922.	

CONFIDENTIAL INFORMATION
 THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE
 OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

LUMEX
INCORPORATED

290 E. HELLEN ROAD
 PALATINE, ILLINOIS 60067
 PHONE: 1-847-359-2790
 WEB: HTTP://WWW.LUMEX.COM

DRAWN BY:	CHECKED BY:	APPROVED BY:	DATE:
SS/DU			11-24-97
PAGE: 1 OF 1			SCALE: N/A