



OFD-MRM790-2F









290 E. HELLEN ROAD PALATINE, ILLINOIS 60067 PHONE: (847) 359-2790 WEB: http://www.lumex.com

RELIABILITY NOTE

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE.

CONFIDENTIAL INFORMATION
THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF

LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX

INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION

CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

DRAWN BY:

CHECKED BY: APPROVED BY: DATE: 2-22-00

PAGE: 1 OF 1 SCALE: N/A

PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

CHARTS

PART NUMBER

OED-MRM790-2F

REV.

TM/DU