

RIGHT ANGLE, SURFACE MOUNT, TWO HIGH FAULT INDICATOR, DESIGNED FOR USE WITH SML-LX1206 SERIES LED.

IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



GB/CK

DRAWN BY: CHECKED BY: APPROVED BY:

DATE: 6.27.03 PAGE: 1 OF 2 SCALE: N/A