



DRAWN BY:	CHECKED BY:	APPROVED BY:	DATE: 01.10.08
JN			PAGE: 1 OF 2
			SCALE: N/A

UNCONTROLLED DOCUMENT

PART NUMBER
LCD-H801M21TR-1

REV.



PIN	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
COM1	COM1				S4	S5	1B	1A	2B	2A	3B	3A	4B	4A	5B	5A	6B	6A	7B	7A	8B	8A
COM2		COM2			S3	S6	1G	1F	2G	2F	3G	3F	4G	4F	5G	5F	6G	6F	7G	7F	8G	8F
COM3			COM3		S2	S7	1C	1E	2C	2E	3C	3E	4C	4E	5C	5E	6C	6E	7C	7E	8C	8E
COM4				COM4	S1	S8	1P	1D	2P	2D	3P	3D	4P	4D	5P	5D	6P	6D	7P	7D	8P	8D

2.00 [0.079]

*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X=±1 (±0.039), X.X=±0.5 (±0.020), X.XX=±0.25 (±0.010), X.XXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). MIN= +DECIMAL PRECISION MAX.= +0.00 -0.00 -DECIMAL PRECISION

REV.

PART NUMBER
LCD-H801M21TR-1

CONFIDENTIAL INFORMATION
THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE
OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

LUMEX
Creating LED and LCD Solutions Together™

290 E. HELEN ROAD
PALATINE, IL 60067-6976
PHONE: +1.847.359.2790
US WEB: www.lumex.com
TW WEB: www.lumex.com.tw

DRAWN BY:

JN

CHECKED BY:

APPROVED BY:

DATE: 01.10.08

PAGE: 2 OF 2

SCALE: N/A

8 DIGIT CUSTOM LCD PANEL, TN, REFLECTIVE,
12:00 VIEW, 1/4 DUTY, 1/3 BIAS, 3V A.C.,
22 PINS, WIDE OPERATING TEMP.