


REV.







## NOTES:

- 1. RECOMENDED LED: SNL-LX1206, SINGULAR COLOR, SML-LX1210, BI-COLOR.
- 2. THIS END IS DIFFUSED.

\*UNCONTROLLED DOCUMENT THERMSE SPECIFIC TOLERANCES PER DECIMAL PRECISION ARE:  $X=\pm1$  ( $\pm0.038$ ),  $X.X=\pm0.5$  ( $\pm0.020$ ),  $X.XX=\pm0.25$  ( $\pm0.010$ ),  $X.XXX=\pm0.127$  ( $\pm0.0106$ ). LEAD SZE= $\pm0.05$  (0.012), LEAD LENGTH= $\pm0.75$  ( $\pm0.030$ ), MIN= $\pm0.010$  PRECISION MAX= $\pm0.010$  MAX= $\pm0.$ 

REV.	part number LPA—C011304S—2	CONFIDENTIAL INFORMATION THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC. THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HERBIN CONFIDENTIAL AND SHALL FROTECT SAME IN WHOLE OR IN PART FRON DISCUSSIVE AND DISSIDMINATION TO ALL THIRD PARTIES.	No form Streener to Mark Sin day			
	1.5mm ROUND LIGHT PIPE.	CUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FALLING. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.	DRAWN BY:		APPROVED BY: DATE PAGE SCAL	: 4.D9.05 : 1 OF 1