PART NUMBER REV. UNCONTROLLED DOCUMENT COMPANY CONFIDENTIAL LPA-LXR128 PRELIMINARY IN P/N DIR 50 20.18 33. 198.85 101.73 CM C3 C3 UNCONTROLLED DOCUMENT

> PART NUMBER LPA-LXR128

REV

CUSTOM FIGURE 8 LIGHTPIPE

CONFIDENTIAL INFORMATION

*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X=`1 (`0.039), XX='0.5 (`0.020), XXX='0.25 (`0.010), XXXX='0.127 (`0.005). LEAD SIZE='0.05 (`0.002), LEAD LENGTH='0.75 (`0.030). MIN= +DECIMAL PRECISION -DECIMAL PRECISION -DE

THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.




PALATINE, IL 60067-6976 PHONE: +1.847.359.2790

US WEB: www.lumex.com TW WEB: www.lumex.com.tw

DRAWN BY: JN

CHECKED BY: APPROVED BY: DATE: 11/6/2008

PAGE: 1 of 1 SCALE: N/A



LPA-LXR128

CUSTOM FIGURE 8 LIGHTPIPE

THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com

TW WEB: www.lumex.com.tw

DRAWN BY: JN

CHECKED BY: APPROVED BY:

DATE: 11/6/2008


PAGE: 1 of 1 SCALE: N/A


UNCONTROLLED DOCUMENT COMPANY CONFIDENTIAL


PART NUMBER

LPA-LXR128


PRELIMINARY IN P/N DIR








Н





(3) (3) UNCONTROLLED DOCUMENT

*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X=`1 (`0.039), XX='0.5 (`0.020), XXX='0.25 (`0.010), XXXX='0.127 (`0.005). LEAD SIZE='0.05 (`0.002), LEAD LENGTH='0.75 (`0.030). MIN= +DECIMAL PRECISION -DECIMAL PRECISION -DE

CONFIDENTIAL INFORMATION

THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com TW WEB: www.lumex.com.tw

DRAWN BY:

CHECKED BY:

APPROVED BY: DATE: 11/6/2008

PAGE: 1 of 1 SCALE: N/A

REV.

CUSTOM FIGURE 8 LIGHTPIPE

LPA-LXR128

PART NUMBER

REV


JN


UNCONTROLLED DOCUMENT COMPANY CONFIDENTIAL

PART NUMBER


LPA-LXR128

PRELIMINARY IN P/N DIR






L-L (1:1)



REV

J-J (1:1)



CM C3 C3 UNCONTROLLED DOCUMENT

*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X=`1 (`0.039), XX='0.5 (`0.020), XXX='0.25 (`0.010), XXXX='0.127 (`0.005). LEAD SIZE='0.05 (`0.002), LEAD LENGTH='0.75 (`0.030). MIN= +DECIMAL PRECISION -DECIMAL PRECISION -DE

PART NUMBER LPA-LXR128

101.95

CUSTOM FIGURE 8 LIGHTPIPE

CONFIDENTIAL INFORMATION

96.40

THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com

TW WEB: www.lumex.com.tw

DRAWN BY: JN

CHECKED BY: APPROVED BY: DATE: 11/6/2008

PAGE: 1 of 1 SCALE: N/A

REV.