

UNCONTROLLED DOCUMENT


PART NUMBER


LPB-R0112051S-ARW






PCB LAYOUT








NOTES:

- 1. OVERLAY LXP-OLO1120551S-ARW
- 2. RECOMMEND SML-LX2832 SERIES LED.
- 3. WINDOW TO BE MILKY WHITE DIFFUSED.



REV.

PART NUMBER

LPB-R0112051S-ARW

20 x 5mm LIGHT BAR WITH ARROW OVERLAY.

CONFIDENTIAL INFORMATION
THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com

TW WEB: www.lumex.com.tw

DRAWN BY:

CHECKED BY: APPROVED BY: DATE: 08.25.09

PAGE: 1 OF 1 SCALE: N/A