UNCONTROLLED DOCUMENT

SC:0.50

PART NUMBER

LPF-R0113031D-M4


PRELIMINARY IN P/N DIR


RECOMMENDED LEDS:


NOTES:


1. SSL-LX3034SUGD.

1. LEDS ARE SEPERATE FROM LIGHT PIPE.









UNCONTROLLED DOCUMENT

*UNILESS OTHERWISE SPECIFIED TOLERANCES PER DECINAL PRECISION ARE: X=±1 (±0.039), XX=±0.5 (±0.020), XXX=±0.25 (±0.010), XXXX=±0.127 (±0.005). LEAU SIZE=±0.05 (±0.002), LEAU ENGIN=±0.75 (±0.000), MN=+0.000 (

REV.

PART NUMBER

LPF-R0113031D-M4

CONFIDENTIAL INFORMATION

THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX NO. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THRO PARTIES.

 $\begin{array}{c} \underline{\text{Reliablity Note}} \\ \text{Our nany years of experience data accumulation indicate that} \end{array}$ SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com TW WEB: www.lumex.com.tw

DRAWN BY:

CHECKED BY: APPROVED BY:

DATE: 7.8.02 PAGE: 1 OF 1 SCALE: N/A

CT