UNCONTROLLED DOCUMENT

NOTES:

PART NUMBER SSA-LLP39793-5


1. WHITE POLYCARBONATE HOLDER.


2. LIGHT PIPES, MATERIAL CLEAR POLYCARBONATE, 8 PCS.


3. TOP SURFACE OF PIPES DIFFUSED.


4. LUMEX NAME AND PART NUMBER 40755-009 TO BE LOCATED ON TOP SURFACE.


5. POSTIONS 6, 7, 8 NO LIGHT PIPE.











UNCONTROLLED DOCUMENT

LEAD LENGTH=±0.75 (±0.030). MIN= +DECIMAL PRECISION MAX.= +0.00 *TOLERANCES PER DECIMAL PRECISION ARE: X=±1 (±0.039), X.X=±0.5 (±0.020), X.XX=±0.25 (±0.010), X.XXX=±0.127 (±0.005).

REV.

PART NUMBER SSA-LLP39793-5

5 UNIT LIGHT PIPE WITH REFLECTOR HOUSING.

Confidential information

The information contained in this document is the property of Lumex No. Except as specifically authorized in Writing by Lumex Inc, the property inc, the proder of this document shall keep all information contained herein confidential and shall protect same in whole or IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



290 E. HELLEN ROAD PALATINE, ILLINOIS 60067 PHONE: (847) 359-2790 WEB: http://www.lumex.com

CHECKED BY: APPROVED BY: DATE: 3-22-00

PAGE: 1 OF 1

REV.

SS/BC

SCALE: N/A