

**ELECTRO-OPTICAL CHARACTERISTIC TA=25°C**

PARAMETER		MIN	TYP	MAX	UNITS	TEST COND
<b>SUPPLY VOLTAGE</b>	VDD	-	5	-	V	-
<b>PEAK WAVELENGTH (PER DOT)</b>	R	-	630	-	nm	If=5mA
	G	-	520	-		
	B	-	470	-		
<b>LUMINOUS INTENSITY (PER DOT)</b>	R	72	-	180	mcd	If=5mA
	G	180	-	360		
	B	28.5	-	72		
<b>POWER CONSUMPTION</b>		-	-	1.9	W	-
<b>VIEWING ANGLE (PER DOT)</b>		-	120	-	2x theta1/2	If=5mA
<b>EPOXY LENS FINISH</b>		WATER CLEAR				

**COMPONENT**

ITEM	P/N	QTY.
1	SMR-6656-24-RGB	1
2	LDR-CONTROLLER-LITE	1

\*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X=±1 (±0.039), X.X=±0.5 (±0.020), X.XX=±0.25 (±0.010), X.XXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). MIN= <sup>+DECIMAL PRECISION</sup>/<sub>-0.00</sub> MAX= <sup>+0.00</sup>/<sub>-DECIMAL PRECISION</sub>

**ezDisplay RGB Ring and Stripe Command List**

Code	Function	Driver IC embedded RGB LED Ring and Stripe has 256 grayscale for each primary color (R,G,B)	
		Instruction of AT Command mode	API for C code
<b>0xc0</b>	Set the color of desinated pixel	1. atc0=(address of pixel, grayscale of R 0~255, grayscale of G 0~255, grayscale of B 0~255) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atc0=(0,255,255,0)	<pre>printf("atc0=(%d,%d,%d,%d)",address,R,G,B); while (USART_ReceiveData(UART1)!='E') {}</pre>
<b>0xc1</b>	Set the color of desinated pixels within a section	1. atc1=(address of the start pixel, address of the end pixel, grayscale of R 0~255, grayscale of G 0~255, grayscale of B 0~255) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atc1=(18,25,0,100,0)	<pre>printf("atc1=(%d,%d,%d,%d,%d)",address1,address2,R,G,B); while (USART_ReceiveData(UART1)!='E') {}</pre>
<b>0xc2</b>	Set the color randomly for each pixel of ring	1. atc2=( 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atc2=( 	<pre>printf("atc2=()"); while (USART_ReceiveData(UART1)!='E') {}</pre>
<b>0xc3</b>	Turn the ring pixels clockwise one round	1. atc3=(speed of turning 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atc3=(10)	<pre>printf("atc3=(%d)",speed); while (USART_ReceiveData(UART1)!='E') {}</pre>
<b>0xc4</b>	Turn the ring pixels counter clockwise one round	1. atc4=(speed of turning 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atc4=(10)	<pre>printf("atc4=(%d)",speed); while (USART_ReceiveData(UART1)!='E') {}</pre>
<b>0xc5</b>	Turn one pixels Clockwise	1. atc5=(speed of shifting 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atcb=(10)	<pre>printf("atc5=(%d)",speed); while (USART_ReceiveData(UART1)!='E') {}</pre>
<b>0xc6</b>	Turn one pixels Counter clockwise	1. atc6=(speed of shifting 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atcc=(10)	<pre>printf("atc6=(%d)",speed); while (USART_ReceiveData(UART1)!='E') {}</pre>


\*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X=±1 (±0.039), X.X=±0.5 (±0.020), X.XX=±0.25 (±0.010), X.XXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). MIN= <sup>+DECIMAL PRECISION</sup> -0.00 MAX.= <sup>+0.00</sup> -DECIMAL PRECISION

Code	Function	Driver IC embedded RGB LED Ring and Stripe has 256 grayscale for each primary color (R,G,B)	
		Instruction of AT Command mode	API for C code
<b>0xc7</b>	Flash one desinated pixle	1. atc7=(address of pixel, speed of flashing 1~100) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atc7=(0,50)	printf("atc7=(%d,%d)",address,speed); while (USART_ReceiveData(UART1)!= 'E') {}
<b>0xc8</b>	Flash desinated pixels within a section	1. atc8=(address of the start pixel, address of the end pixel, speed of flashing 1~100) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atc8=(2,5,50)	printf("atc8=(%d,%d,%d)",address1,address2,speed); while (USART_ReceiveData(UART1)!= 'E') {}
<b>0xc9</b>	Flash whole ring	1. atc9=(speed of flashing 1~100) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atc9=(50)	printf("atc9=(%d)",speed); while (USART_ReceiveData(UART1)!= 'E') {}
<b>0xca</b>	Breath effect of whole ring for 7 major colors	1. atca=(0 or 1 for R, 0 or 1 for G, 0 or 1 for B) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atca=(0,0,1)	printf("atca=(%d,%d,%d)",R,G,B); while (USART_ReceiveData(UART1)!= 'E') {}
<b>0xcd</b>	Set the dynamic fuction's color	1. atcd=(grayscale of R 0~255, grayscale of G 0~255, grayscale of B 0~255) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atcd=(128,9,18)	printf("atcd=(%d,%d,%d)",R,G,B); while (USART_ReceiveData(UART1)!= 'E') {}
<b>0xce</b>	Set the dynamic fuction's speed	1. atce=(speed 1~100) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atce=(5)	printf("atce=(%d)",speed); while (USART_ReceiveData(UART1)!= 'E') {}
<b>0xcf</b>	Set the pixel number of ring	1. atcf=(number of pixels of ring 1~120) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atcf=(48)	printf("atcc=(%d)",Number_of_Pixel); while (USART_ReceiveData(UART1)!= 'E') {}

\*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X=±1 (±0.039), X.X=±0.5 (±0.020), X.XX=±0.25 (±0.010), X.XXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). MIN= <sup>+DECIMAL PRECISION</sup>/<sub>-0.00</sub> MAX. = <sup>+0.00</sup>/<sub>-DECIMAL PRECISION</sub>

Code	Function	Driver IC embedded RGB LED Ring and Stripe has 256 grayscale for each primary color (R,G,B)	
		Instruction of AT Command mode	API for C code
<b>0xd0</b>	Clear display	1. atd0=() 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atd0=()	printf("atd0=()"); while (USART_ReceiveData(UART1) != 'E') {}
<b>0x10</b>	Fill pixel one by one, strat from last pixel	1. at10=(grayscale of R 0~255, grayscale of G 0~255, grayscale of B 0~255, speed of filling 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> at10=(0,105,0,5)	printf("at10=(%d,%d,%d,%d)",R,G,B,speed); while (USART_ReceiveData(UART1) != 'E') {}
<b>0x11</b>	Fill pixel one by one, strat from first pixel	1. at11=(grayscale of R 0~255, grayscale of G 0~255, grayscale of B 0~255, speed of filling 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> at11=(0,105,0,2)	printf("at11=(%d,%d,%d,%d)",R,G,B,speed); while (USART_ReceiveData(UART1) != 'E') {}
<b>0x12</b>	Stack pixel one by one clockwise then turn off pixel counterclockwise	1. at12=(grayscale of R 0~255, grayscale of G 0~255, grayscale of B 0~255, speed of stacking 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> at12=(0,10,255,5)	printf("at12=(%d,%d,%d,%d)",R,G,B,speed); while (USART_ReceiveData(UART1) != 'E') {}
<b>0x13</b>	Stack pixel one by one counterclockwise then turn off pixel clockwise	1. at13=(grayscale of R 0~255, grayscale of G 0~255, grayscale of B 0~255, speed of stacking 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> at13=(255,0,0,10)	printf("at13=(%d,%d,%d,%d)",R,G,B,speed); while (USART_ReceiveData(UART1) != 'E') {}
<b>0x14</b>	Two pixels collision then firework	1. at14=(grayscale of R 0~255, grayscale of G 0~255, grayscale of B 0~255, speed of stacking 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> at14=(0,255,0,10)	printf("at14=(%d,%d,%d,%d)",R,G,B,speed); while (USART_ReceiveData(UART1) != 'E') {}
<b>0x15</b>	Two stack pixels collision then firework	1. at15=(grayscale of R 0~255, grayscale of G 0~255, grayscale of B 0~255, speed of stacking 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> at15=(0,255,0,10)	printf("at15=(%d,%d,%d,%d)",R,G,B,speed); while (USART_ReceiveData(UART1) != 'E') {}

\*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X=±1 (±0.039), X.X=±0.5 (±0.020), X.XX=±0.25 (±0.010), X.XXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). MIN= <sup>+DECIMAL PRECISION</sup> -0.00 MAX. = <sup>+0.00</sup> -DECIMAL PRECISION

 <p>425 N. GARY AVE. CAROL STREAM, IL 60188 PHONE : 800-278-5666 FAX : 630-315-2150 WEB : WWW.LUMEX.COM</p>	ez RING SERIES, Ø66(Ø56)*2.3, 24 DOT RGB LEDs, UART INTERFACE, DC 5V.	DATE : 2018.10.03	DRAWN BY : C.C.	
	<b>**THE SPECIFICATIONS MAY CHANGE AT ANY TIME WITHOUT NOTICE.**</b>	PAGE : 4 OF 5	CHKD BY : E.C.	
	<b>CONFIDENTIAL INFORMATION</b>	SCALE : NTF	APRVD BY : G.Y.	
	<b>THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.</b>	UNIT : mm [INCH]		

Code	Function	Driver IC embedded RGB LED Ring and Stripe has 256 grayscale for each primary color (R,G,B)	
		Instruction of AT Command mode	API for C code
0x16	Two pixels collision then bounce back	1. at16=(grayscale of R 0~255, grayscale of G 0~255, grayscale of B 0~255, speed of stacking 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> at16=(255,255,255,10)	<pre>printf("at16=(%d,%d,%d,%d)",R,G,B,speed); while (USART_ReceiveData(UART1)!='E') {}</pre>
0x17	Two stack pixels collision then fade back	1. at17=(grayscale of R 0~255, grayscale of G 0~255, grayscale of B 0~255, speed of stacking 1~30) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> at17=(0,255,100,10)	<pre>printf("at17=(%d,%d,%d,%d)",R,G,B,speed); while (USART_ReceiveData(UART1)!='E') {}</pre>
0xf2	Set the Dimming level  * Only available for Dimmable LEDs	1. atf2=(Dimming level 0~31) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <example> atf2=(7)	<pre>printf("atf2=(%d)",Dimming); while (USART_ReceiveData(UART1)!='E') {}</pre>
0xfd	Set the dynamic function	1. atfd=(Function Code 0~20) 2. Wait until receive a device available byte ('E') from Ring or Stripe  <Function code> 0 : Stop the auto run back to static mode 1~20 are auto run mode. The display speed and color can be determined by atcc and atcd command accordingly 1: Breath (for red, green, blue, yellow, cyan, magenta & white only) 2: Randomly color display for whole ring 3: Turn one pixel clockwise 4: Turn one pixel counter clockwise 5: Turn comet section pixels clockwise (for red, green, blue, yellow, cyan, magenta & white only) 6: Turn comet section pixels counter clockwise (for red, green, blue, yellow, cyan, magenta & white only) 7: Comet section pixels bounce around (for red, green, blue, yellow, cyan, magenta & white only) 8: Turn ring display memory data clockwise (Ring display memory can be determined by atc0 or atc1command) 9: Turn ring display memory data counter clockwise (Ring display memory can be determined by atc0 or atc1command) 10: Flash whole ring 11: Fill pixel one by one start from last pixel 12: Fill pixel one by one start from first pixel 13: Fill pixel one by one clockwise then disappear one by one counter clockwise 14: Fill pixel one by one clockwise then disappear one by one clockwise 15: Show the ring display memory data one by one then disappear one by one counter clockwise 16: Show the ring display memory data one by one then disappear one by one clockwise 17: Two pixels collide then firework effect 18: Two section pixels collide then firework effect 19: Two pixels crossing 20: Two pixels collide then bounce back	<pre>printf("atfd=(%d)",Function); while (USART_ReceiveData(UART1)!='E') {}</pre>

\*UNLESS OTHERWISE SPECIFIED TOLERANCES PER DECIMAL PRECISION ARE: X=±1 (±0.039), X.X=±0.5 (±0.020), X.XX=±0.25 (±0.010), X.XXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). MIN= <sup>+DECIMAL PRECISION</sup> -0.00 MAX= <sup>+0.00</sup> -DECIMAL PRECISION